

Site Details: Bassingbourn-cum-Kneesworth Parish Council
Pavilion Willmot Recreation Ground
South End
Bassingbourn
Herts
SG8 5NH

Certificate of Inspection

Fire Extinguisher Service

Tel No: **Email:**

I/we being the competent person(s) responsible (as indicated by my/our signatures below) for the servicing of the fire extinguishers, particulars of which are set out below, CERTIFY that the said work for which I/we have been responsible complies to the best of my/our knowledge and belief with the recommendations of BS5306-3 periodic inspection, except for the variations, if any, stated in this certificate.

No signage:

2 x water required
1 x blanket required
1 x carbon dioxide required

Fire Extinguisher Service	-	-
Is email address correct?		Yes
Date of last service?	7/25	Comments
Date of next service?	6/27	Comments
Have you shown your ID?		Yes
Total fire extinguishers serviced?		4
Quantity of Water fire extinguishers basic service?		2
Quantity of Water fire extinguishers extended serviced?		Nil
Quantity of Water fire extinguishers non-conforming?		Nil
Quantity of AFFF fire extinguishers basic service?		Nil
Quantity of AFFF fire extinguishers extended service?		Nil
Quantity of AFFF fire extinguishers none conforming?		Nil
Quantity of Dry Powder fire extinguishers basic service?		Nil
Quantity of Dry Powder fire extinguishers extended service?		Nil
Quantity of Dry Powder fire extinguishers none conforming?		Nil
Quantity of Co2 fire extinguishers basic service?		1
Quantity of Co2 fire extinguishers overhaul?		Nil
Quantity of Co2 fire extinguishers none conforming?		Nil
Quantity of fire blankets basic service?		1
Quantity of fire blankets none conforming?		Nil
Quantity of AR Foam fire extinguishes basic service?		Nil
Quantity of AR Foam fire extinguishes extended service?		Nil
Quantity of AR Foam fire extinguishes none conforming?		Nil
Quantity of L2 Foam fire extinguishes basic service?		Nil
Quantity of L2 Foam fire extinguishes extended service?		Nil
Quantity of L2 Foam fire extinguishes none conforming?		Nil
Log book completed?		Yes
Fire safety signage compliant?		Comments

Qty Part

Fire Extinguisher Report

No signage:

2 x water required
1 x blanket required
1 x carbon dioxide required

Work completed

29/06/2026 10:47:02 - Created by Andy Gray



Cert No **48876**

Account No **10960**

Date **29/06/2026**



Site Details: Bassingbourn-cum-Kneesworth Parish Council
Pavilion Willmot Recreation Ground
South End
Bassingbourn
Herts
SG8 5NH

Certificate of Inspection

Fire Extinguisher Service

Tel No: **Email:**
I/we being the competent person(s) responsible (as indicated by my/our signatures below) for the servicing of the fire extinguishers, particulars of which are set out below, CERTIFY that the said work for which I/we have been responsible complies to the best of my/our knowledge and belief with the recommendations of BS5306-3 periodic inspection, except for the variations, if any, stated in this certificate.
Extinguisher service

Confirmed by Maisy Person
Approx 4 ext

Materials Used/Required:

Engineer

Customer

The extent of liability of the signatory is limited to the system described above.

Note: Andy Gray 29/06/2026 13:59:27 maisie 29/06/2026 13:59:38

The recommended period between successive inspection and service visits must not exceed 12 months for the fire alarm.

If a risk assessment dictates more frequent service visits arrangements should be made.
If these recommendations are not implemented, it should be considered that this equipment is no longer compliant with this part of the BS 5306 standard.